Clear Epoxy Primer

SECTION 1: PRODUCT AND COMPANY IDENTIFICATION - Part A & B

PRODUCT NAME: Clear Epoxy Primer

SYNONYMS: N/A PRODUCT CODES: SKU 20200

MANUFACTURER: Shield Products, Inc.

DIVISION: N/A

ADDRESS: 6010 NW 99th Ave. Doral, Florida 33178

EMERGENCY PHONE: 904-880-6060 CHEMTREC PHONE: 800-424-9300

SECTION 1 NOTES:

SECTION 2: COMPOSITION/INFORMATI	ON ON INGR	EDIENTS - Part	A			
CHEMICAL INGREDIENT	CAS NUMBER	OSHA PEL	ACGIH TLV	VAPOR PRESS mmHg @ TEMP	SARA SEC. 313 *	WT. PERCENT
METHYL ISOBUTYL KETONE	108-10-1	100 PPM	50 PPM	28.0@68	YES	5 - 15
XYLENE	1330-20-7	100 PPM	100 PPM	6.0@68	YES	<5
TOLUENE	108-88-3	100 PPM	50 PPM	22.0@68	YES	5
ETHYLENE GLYCOL BUTYL ETHER	111-76-2	25 PPM (Skin)	25 PPM (Skin)	0.6@68	YES	5 - 10
N-BUTYL ALCOHOL	71-36-3	50 PPM ` ´	` ,	5.5@68	YES	5
AROMATIC HYDROCARBON SOLVENT	64742-95-6	100 PPM	100 PPM	2.0@68		5 - 10
1,2,4-TRIMETHYLBENZENE	95-63-6	25 PPM	25 PPM	N/A	YES	<5
SILICON DIOXIDE	7631-86-9	20 MPPCF	10 MG/M3	N/A		0 - 5

FILE NO.: DM900

MSDS DATE: 03/15

^{*} Ingredients marked YES are subject to the reporting requirements of the Superfund Amendments and Reauthorization Act (SARA) Section 313, 40 CFR 372.

SECTION 2 NOTES:

SECTION 2: COMPOSITION/INFORMATION ON INGREDIENTS - Part B										
CHEMICAL INGREDIENT	CAS NUMBER	OSHA PEL	ACGIH TLV	VAPOR PRESS mmHg @ TEMP	SARA SEC. 313 *	WT. PERCENT				
POLYAMIDE RESIN	68410-23-1	Unkown	Unknown	N/A		85				
XYLENE	1330.20-7	100 ppm	100 ppm	6.0@88	YES	15				
N-SIJ YL ALCOHOL	7t-36-3	50 PPM	• •	55@68	YES	15				
GLACIIAL ACETIC ACID	8419-7	10 PPM		11.0@68		<5				

SECTION 2 NOTES:

SECTION 3: HAZARDS IDENTIFICATION - Part A & B

POTENTIAL HEALTH EFFECTS

EYES: Severe irritation, redness, tearing, blurred vision. May be a sensitizer in some individuals.

SKIN: Liquid can be absorbed through the skin resulting in symptoms similar to the inhalation effects

INGESTION: Gastrointestinal irritation, nausea, vomiting and diarrhea. Aspiration into the lungs during ingestion or vomiting may cause mild to severe pulmonary injury and possibly even death.

Clear Epoxy Primer

FILE NO.: DM900 MSDS DATE: 03/15

INHALATION: Anesthetic, excessive inhalation can cause irritation of the respiratory tract, or acute nervous system depression characterized by headache, dizziness, staggering gait, confusion, unconsciousness, coma and even asphyxiation.

ACUTE HEALTH HAZARDS: Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents may be harmful or fatal.

SECTION 3 NOTES:

SECTION 4: FIRST AID MEASURES - Part A & B

EYES: flush immediately

with large amounts of water for at least 15 minutes. Take to a physician for medical treatment.

SKIN: Wash affected areas with soap and water. Remove and launder contaminated clothing. Consult a physician if needed.

INGESTION: Drink 1 or 2 glasses of water to dilute. Do not induce vomiting. Get medical help immediately.

SECTION 4 NOTES:

SECTION 5: FIRE-FIGHTING MEASURES - Part A

FLAMMABLE LIMITS IN AIR, UPPER: 10.6 (% BY VOLUME) LOWER: 0.09

FLASH POINT: 74 F METHOD USED: Setaflash

EXTINGUISHING MEDIA: FOAM, ALCOHOL FOAM, CO2, DRY CHEMICAL

SPECIAL FIRE FIGHTING PROCEDURES: During emergency conditions overexposrue to decomposition products may cause a health hazard. Sypmtoms may not be immediately apparent. Obtain medical attention. Keep containers tightly closed. Isolate from heat, sparks, and open flame.

UNUSUAL FIRE AND EXPLOSION HAZARDS: Closed containers may explode when exposed to extreme heat. Application to hot surfaces requires special precautions. Full protective equipment including self-contained breathing apparatus should be used. Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up.

HAZARDOUS DECOMPOSITION PRODUCTS:

SECTION 5 NOTES:

SECTION 5: FIRE-FIGHTING MEASURES - Part B

FLAMMABLE LIMITS IN AIR, UPPER: 19.9 (% BY VOLUME) LOWER: 1.0

FLASH POINT: 96 F

EXTINGUISHING MEDIA: FOAM, ALCOHOL FOAM, CO2, DRY CHEMICAL.

Clear Epoxy Primer

MSDS DATE: 03/15 SPECIAL FIRE FIGHTING PROCEDURES: During emergency conditions overexposure to decomposition products may cause a

FILE NO.: DM900

health hazard. Symptons may not be immediately apparent

Obtain medical attention. Keep containers tightly closed, isolate from heat, sparks and open flame.

UNUSUAL FIRE AND EXPLOSION HAZARDS: Closed containers may explode when exposed to extreme heat Application to heated surfaces require special precautions. Full Protective equipment including self contained breathing apparatus

should be used. Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build up.

SECTION 5 NOTES:

SECTION 6: ACCIDENTAL RELEASE MEASURES - Part A & B

ACCIDENTAL RELEASE MEASURES: Remove all sources of ignition (flame, hot surfaces, and electrical, static or frictional sparks). Avoid breathing vapors. Ventilate area. Contain and remove with inert absorbent and non-sparking tools.

SECTION 6 NOTES:

SECTION 7: HANDLING AND STORAGE - Part A & B

HANDLING AND STORAGE: Do not store above 120 F. Store large quantities only in buildings designed to comply with OSHA 1910.106. Keep closures tight and container upright to prevent leakage. Do not store or use near heat, sparks or flame. Never use pressure to empty. Drum must not be washed out or used for other purposes. Drums of this material should be grounded when pouring.

OTHER PRECAUTIONS: Do not get in eyes. Avoid skin contact. Can cause allergic respiratory reaction. Can cause allergic skin reaction. Prevent prolonged or repeated breathing of vapors or spray mist. Avoid breathing of sanding dust. Wash contaminated clothing thoroughly. Wash skin thoroughly with soap and water after handling. Close container after each use. Do not transfer this product to unlabeled containers. Do not handle until the manufacturer's safety precautions have been read and understood. Keep out of reach of children.

SECTION 7 NOTES:

SECTION 8: EXPOSURE CONTROLS/PERSONAL PROTECTION - Part A & B

VENTILATION: All application areas should be ventilated in accordance to OSHA regulation 29 CFR 1910.94, 1910.107, 1910.108. Remove decomposition products formed during welding or flame cutting on surface coated with this product. If baking, vent fumes.

RESPIRATORY PROTECTION: Use a NIOSH-approved respirator to prevent overexposure, when exposure exceeds occupational exposure limits (Section II). Use either an atmosphere-supplying respirator or an air-purifying respirator for organic vapors in compliance with 29 CFR 1910.134, with provision for mist removal if conditions so indicate.

EYE PROTECTION: Safety eyewear including splashguards or side shields recommended.

SKIN PROTECTION: Use protective outerwear and prevent prolonged skin contact with contaminated clothing.

Clear Epoxy Primer

FILE NO.: DM900 MSDS DATE: 03/15

WORK HYGIÉNIC PRACTICES: Avoid breathing vapors and contact with skin. Wash skin thoroughly before breaks and meals and at end of work period.

SECTION 8 NOTES:

SECTION 9: PHYSICAL AND CHEMICAL PROPERTIES - Part A

APPEARANCE: Liquid

ODOR: Typical paint solvent odor

PHYSICAL STATE:

BOILING POINT: 228 F

VAPOR DENSITY (AIR = 1): Heavier than air

SPECIFIC GRAVITY (H2O = 1): 1.4 EVAPORATION RATE: Slower than ether

BASIS (=1):

SOLUBILITY IN WATER: Negligible

VOLATILE ORGANIC COMPOUNDS (VOC): 4.3 lb/gal

SECTION 9 NOTES:

SECTION 9: PHYSICAL AND CHEMICAL PROPERTIES - Pary B

APPEARANCE: Liquid

ODOR: Typical paint solvent odor BOILING POINT: 240 F VAPOR DENSITY (AIR = 1): Heavier than air SPECIFIC GRAVITY (H2O = 1): 0.9 EVAPORATION RATE: Slower than ether

BASIS (=1):

SOLUBILITY IN WATER: Negligible

VOLATILE ORGANIC COMPOUNDS (VOC): 2.19 lb/gal

SECTION 9 NOTES:

SECTION 10: STABILITY AND REACTIVITY - Part A & B

STABILITY: Stable

CONDITIONS TO AVOID (STABILITY): High Temperatures

INCOMPATIBILITY (MATERIAL TO AVOID): Oxidizing materials

Clear Epoxy Primer HAZARDOUS DECOMPOSITION OR BY-PRODUCTS: May produce hazardous fumes when heated to decomposition as in welding.

HAZARDOUS POLYMERIZATION: Will not occur.

SECTION 10 NOTES:

SECTION 11: DISPOSAL CONSIDERATIONS - Part A & B

WASTE DISPOSAL METHOD: Dispose of in accordance with local, state and federal regulations. Incinerate in approved facility. Do not incinerate closed containers.

FILE NO.: DM900

MSDS DATE: 03/15

SECTION 11 NOTES: